

3/24/92

SITE NAME:

(attach a copy of the Site Update from the NPL Notebook)
Dayco Corp./L.E. Carpenter

RPM: J. Josephs

Section: NNJS 2

ROD Signature Date: 93/1

Most Recent Draft Document in Preparation or Review: FS
(RI, FS, Proposed Plan, etc.)

Potential Issues or Conflicts with New Jersey DEPE:
(ARARS, new State proposed action levels,
risk determinations, etc.)

Levels of lead, antimony and other metals are elevated due to mining operations which occurred in the area around the turn of the century. The PRP may resist having to remediate metals since there may be high background values in the area at other mines which aren't Superfund sites. DEPE is likely to require some remediation for metals at "hot spots." EPA has not taken a position on this issue.

346895

